



Old

Interchangeable as set

New



Treiber, Puffer und Zylinder für das Gerät geändert, um Rückholprobleme und Doppelklammern zu vermeiden.

Changed driver blade, bumper and cylinder for the tool to avoid problems with the return of the piston and shooting of two staples with on stroke of the piston.

Datum: 10.12.21